Report of Test

LL23502

ORIGINAL REPORT

This test report was issued by LightLab International without alterations or amendments

Activity address: 50 Redcliffe Gardens Drive, Clontarf, Qld, 4019, Australia.

USA west coast LightLab International, LLC, 24825 N. 16th Avenue, Suite 125, Phoenix, AZ, 85085 — Ph : +1 623-434-1499, Fx : +1 623-434-1492, www.lightlabint.com

USA east coast LightLab Int'l Allentown LLC, 905 Harrison Street, Suite 135, Allentown, PA 18103 — Ph: +1 484-273-0705, www.lightlabint.com

Australasia & S.E. Asia LightLab International, 50 Redcliffe Gardens Drive, Clontarf, Queensland, 4019, Australia — Ph : +61 7 3283 7862, www.lightlabint.com (issuing laboratory)

Test Report Number LL23502

Client	Connected Light Solutions
Contact	Remko Verschuur
Address	34-36 Adderley Street East, Lidcombe. NSW. 2141.
Devices Tested	10 x 240 W (nom.) LED Area Lighters. Identified by LightLab as Sample A to J (also identified with test number). GE Cat No.: ALUASN240AWBHSG1D1 (SKU S70372R). The device comprises: Cast aluminium body with grey finish, Two SPL6P22S V1.00 LED PCBs, One Mean Well ELG-240-C1750DA electronic driver.
Nature of Tests	To determine the total circuit power, supply current and power factor of the supplied devices while operating under standard laboratory conditions with the supply set to 250 V 50 Hz. Performance data in accordance with IESNA LM-79-08.
Applicability	This report is applicable only to the samples that were tested.
Sample Selection	This laboratory has not exercised control over the selection of samples to be tested. All testing is performed on the understanding that the significance of the report is limited to the extent to which the test samples are representative of production units.
Procedure	The sample was tested in free air with luminous opening horizontal and face down in a draft free room. The supply voltage and frequency to the control gear was set according to the values in Table 1 and the sample was operated till electrical stability was achieved prior to recording measurements. The relevant measurements are recorded in Table 1. All measurements were performed in a controlled environment of 25 ± 1 ° Celsius.

This test report was issued by LightLab International without alterations or amendments

Activity address: 50 Redcliffe Gardens Drive, Clontarf, Qld, 4019, Australia.

USA west coast LightLab International, LLC, 24825 N. 16th Avenue, Suite 125, Phoenix, AZ, 85085 — Ph : +1 623-434-1499, Fx : +1 623-434-1492, www.lightlabint.com

USA east coast LightLab Int'l Allentown LLC, 905 Harrison Street, Suite 135, Allentown, PA 18103 — Ph: +1 484-273-0705, www.lightlabint.com

Australasia & S.E. Asia LightLab International, 50 Redcliffe Gardens Drive, Clontarf, Queensland, 4019, Australia — Ph : +61 7 3283 7862, www.lightlabint.com (issuing laboratory)

Test Report Number LL23502

Photographs

This test report was issued by LightLab International without alterations or amendments

Activity address: 50 Redcliffe Gardens Drive, Clontarf, Qld, 4019, Australia.

USA west coast LightLab International, LLC, 24825 N. 16th Avenue, Suite 125, Phoenix, AZ, 85085 — Ph : +1 623-434-1499, Fx : +1 623-434-1492, www.lightlabint.com

USA east coast LightLab Int'l Allentown LLC, 905 Harrison Street, Suite 135, Allentown, PA 18103 — Ph: +1 484-273-0705, www.lightlabint.com

Australasia & S.E. Asia LightLab International, 50 Redcliffe Gardens Drive, Clontarf, Queensland, 4019, Australia — Ph : +61 7 3283 7862, www.lightlabint.com (issuing laboratory)

Test Report Number LL23502

This test report was issued by LightLab International without alterations or amendments

Activity address: 50 Redcliffe Gardens Drive, Clontarf, Qld, 4019, Australia.

USA west coast LightLab International, LLC, 24825 N. 16th Avenue, Suite 125, Phoenix, AZ, 85085 — Ph : +1 623-434-1499, Fx : +1 623-434-1492, www.lightlabint.com

USA east coast LightLab Int'l Allentown LLC, 905 Harrison Street, Suite 135, Allentown, PA 18103 — Ph: +1 484-273-0705, www.lightlabint.com

Australasia & S.E. Asia LightLab International, 50 Redcliffe Gardens Drive, Clontarf, Queensland, 4019, Australia — Ph : +61 7 3283 7862, www.lightlabint.com (issuing laboratory)

Test Report Number LL23502

Test Results

Sample ID	Supply voltage (Vac)	Supply frequency (Hz)	Supply current (A)	Supply Power (W)	Power Factor
LL23502A	250	50	0.998	244.5	0.98
LL23502B	250	50	0.998	244.6	0.98
LL23502C	250	50	0.981	240.4	0.98
LL23502D	250	50	0.981	240.6	0.98
LL23502E	250	50	0.979	239.8	0.98
LL23502F	250	50	0.991	242.8	0.98
LL23502G	250	50	0.989	242.4	0.98
LL23502H	250	50	0.992	243.2	0.98
LL23502I	250	50	0.992	243.3	0.98
LL23502J	250	50	0.991	242.9	0.98

Table 1

This test report was issued by LightLab International without alterations or amendments

Activity address: 50 Redcliffe Gardens Drive, Clontarf, Qld, 4019, Australia.

USA west coast LightLab International, LLC, 24825 N. 16th Avenue, Suite 125, Phoenix, AZ, 85085 — Ph : +1 623-434-1499, Fx : +1 623-434-1492, www.lightlabint.com

USA east coast LightLab Int'l Allentown LLC, 905 Harrison Street, Suite 135, Allentown, PA 18103 — Ph: +1 484-273-0705, www.lightlabint.com

Australasia & S.E. Asia LightLab International, 50 Redcliffe Gardens Drive, Clontarf, Queensland, 4019, Australia — Ph : +61 7 3283 7862, www.lightlabint.com (issuing laboratory)

Uncertainties

When calculated at the 95% confidence interval with coverage factor k = 2, the estimated uncertainties are:

Temperature	± 1° Celsius
Electrical Power (ac)	± 0.5%
Electrical Voltage (ac)	± 0.5%
Electrical Current (ac)	± 0.5%
Frequency (Hz) *	± 0.2%
Power Factor	± 0.02

* NATA accreditation does not cover the performance of this service.

Laboratory

Measurements were performed at the LightLab International Brisbane Laboratory.

Date of Tests	14/07/2021 to 16/07/2021
Date of Report	26/07/2021

Authorised Signatory

K Monaghan

Kevin Monaghan

B3067 - ESC Report , Version 1.1, 22 May 2017

This test report was issued by LightLab International without alterations or amendments

Activity address: 50 Redcliffe Gardens Drive, Clontarf, Qld, 4019, Australia.

USA west coast LightLab International, LLC, 24825 N. 16th Avenue, Suite 125, Phoenix, AZ, 85085 — Ph : +1 623-434-1499, Fx : +1 623-434-1492, www.lightlabint.com

USA east coast LightLab Int'l Allentown LLC, 905 Harrison Street, Suite 135, Allentown, PA 18103 — Ph: +1 484-273-0705, www.lightlabint.com

Australasia & S.E. Asia LightLab International, 50 Redcliffe Gardens Drive, Clontarf, Queensland, 4019, Australia — Ph : +61 7 3283 7862, www.lightlabint.com (issuing laboratory)